ITEM	
COLORADO SCOREBOARD 8" (H) x 16'6" (W) –	Total Construction cost - \$291,500
ALSO MOVE THE LOCATION TO OPPOSITE WALL	Total Project Cost - \$468,928 (3 years escalation)
(REPAIR WALL BEHIND EXISTING SCOREBOARD)	Total Project cost \$400,525 (5 years escalation)
(Replaces A08.003 \$22,509)	
NEW LAPTOP INTERFACE SCOREBOARD	COMES WITH THE SCOREBOARD
NEW TIMING EQUIPMENT (CONSOLE, CABLES,	Total Construction cost - \$14,575
PADS) (8)	Total Project Cost - \$23,467 (3 years escalation)
PA SYSTEM (INDOOR SPEAKERS, AUDIO CONSOLE,	Total Construction cost - \$58,300
& MIC) FOR THE FACILITY	Total Project Cost - \$93,786 (3 years escalation)
STARTING BLOCKS with HARNESS (8)	Total Construction cost - \$36,000
, ,	Total Project Cost - \$44,187 (3 years escalation)
STARTING BLOCKS WEDGES (8)	Total Construction cost - \$6,400
(Replaces A08.415 \$23,260)	Total Project Cost - \$7,856 (3 years escalation)
RE-TILE AROUND POOL SHELL & LANE MARKERS	Total Construction cost - \$29,150
	Total Project Cost - \$46,893 (3 years escalation)
RAISE LANE HOOKS TO ALIGN WITH POOL	Total Construction cost - \$16,790
SURFACE (18)	Total Project Cost - \$ 27,010 (3 years escalation)
2 – 24FT COOLING FANS (CEILING MOUNTED) (2)	Total Construction cost - \$25,652
	Total Project Cost - \$ 41,302 (3 years escalation)
REPAINT WALLS OF POOL AREA	Total Construction cost - \$58,300
	Total Project Cost - \$ 93,786 (3 years escalation)
REPLACE POOL LIGHTS W/ LED (8)	Total Construction cost - \$9,328
	Total Project Cost - \$ 15,019 (3 years escalation)
REPLACE SUIT DRYERS (REMOVE WATER FROM	Total Construction cost - \$13,992
THE SUIT) (6)	Total Project Cost - \$ 22,528 (3 years escalation)
(Replaces A08.413 to provide only a new wringer	
\$368)	
REPLACE METAL LOCKERS WITH PLASTIC LOCKERS	Total Construction cost - \$420,000
IN LOCKER ROOMS (350)	Total Project Cost - \$515,519 (3 years escalation)
(Replace A08.410 \$21,102 and A08.419 \$21,102)	
RESURFACE FLOORS IN LOCKER ROOMS WITH	Total Construction cost - \$87,450
NON-SLIP MATERIAL	Total Project Cost - \$140,678 (3 years escalation)
NEW RECORD BOARDS (3) (ACCOMPLISHMENTS)	Total Construction cost - \$8,000
	Total Project Cost - \$ 9,819 (3 years escalation)
REPLACE ELECTRIC WATER HEATER FOR DIVERS	Total Construction cost - \$29,150
	Total Project Cost - \$ 46,934 (3 years escalation)
	(not sure if this system exists but this is for
DEDI ACE CDACKED DIDECTAL O ADOLIND SUFFERCIAL	replacement only)
REPLACE CRACKED PIPES IN & AROUND FILTERS IN	Total Project Cost \$ 03,868 (3 years assolution)
THE MECHANICAL ROOM	Total Project Cost - \$ 93,868 (3 years escalation)
REPLACE/REPAIR CORRODED PIPE NEAR SKIMMER	Total Project Cost \$ 113,642 (2 years assolution)
IN THE MECHANICAL ROOM	Total Project Cost - \$ 112,642 (3 years escalation)
ADD EXHAUST FANS TO PULL OUT HEAT AND	Total Project Cost \$ 46,024 (2 years assolution)
CHLORINE SMELL	Total Project Cost - \$ 46,934 (3 years escalation)

REMOVE ALL METAL EQUIPMENT THAT RUSTS	Total Construction cost - \$291,500
(E.G. BENCHES, PAPER TOWEL DISPENSERS, TOILET	Total Project Cost - \$ 468,928 (3 years escalation)
PAPER DISPENSERS, ETC.) AND REPLACE WITH	
PLASTIC OR OTHER APPROPRIATE MATERIAL	(allowance based upon how much equipment is to
Replaces A08.411 \$4,689 & A08.420 \$28,136	be replaced – could be more or less)
FOYER: CONSIDER IF THIS AREA CAN BE USED TO	Not feasible based upon review of the floor plan
EXPAND SEATING CAPACITY WITHIN THE FACILITY.	
INVESTIGATE HOW TO EXPAND SEATING	Not feasible based upon review of the floor plan
	and site plan. Only area we might be able to
New A02.520 800 SF Addition for seating \$652,688	provide an addition is on the side of the pool at
	one end of the lanes – not preferred for seating

Total Approved Projects \$1,609,610 (eliminated 5K SF addition for lockers)

Additional Value of Projects Revised & Added \$2,972,772 (includes seating) *

Value of Projects Potentially Replaced \$121,116 *

Total Swim Center Cost If New Projects Approved \$4,461,266

^{*} This amount represents the projects that would be replaced by the revised projects

^{*} This amount represents line items A08.500 – A08.520, which have not been included in the package to date.